

**DEPARTMENT OF TRANSPORTATION****DIVISION OF ENGINEERING SERVICES**

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch  
690 Walnut Ave. St. 150  
Vallejo, CA 94592-1133  
(707) 649-5453  
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-003130**Date Inspected:** 26-Jun-2008**Project Name:** SAS Superstructure**OSM Arrival Time:** 1400**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 2330**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Sun Wei/Li Yanhua**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG**Summary of Items Observed:**

The Caltrans Quality Assurance (QA) Inspector Roscoe Dixon was present at the time requested to randomly observe welding and associated operations being performed for the Orthotropic Box Girders (OBG).

The QA Inspector observed ZPMC qualified welder Dong Yi Qun ID 059450 utilizing WPS-345-FCAW-2G (2F) Repair to perform Flux Core Arc Welding (FCAW) repairs of deck panel Partial Joint Penetration (PJP) welds on DP030-001 and DP070-001.

**Bay 3 – Heavy Duty Machinery Shop**

The QA Inspector Dixon was informed by ZPMC QC Inspector Mr. Wang Lu that ZPMC CWI Inspector CWI Li Yanhua, and Sun Wei and ABF personnel were about to perform an R2 visual repair inspection on deck panel DP077-001 and DP080-001 and requested that a Caltrans QA Inspector also performed a visual inspection on the deck panel.

After an agreement was reached by all parties for the repairs which needed to be made on the deck panel the QA Inspector identified the repairs to be completed as R2 inspections by marking the yellow tag which is pasted to the outside U-Ribs on the deck panel.

The QA Inspector observed four ZPMC personnel performing grinding of deck panel repairs, one welder performing FCAW welding on deck panel for repair of welds, one CWI Inspector, one personnel performing preheat of areas to be welded, and two ABF QC personnel identified as Kevin Chen and Ding Baohua.

---

## WELDING INSPECTION REPORT

( Continued Page 2 of 2 )

---

The deck panel repair welding in the progress generally appeared to conform to contract specifications.

### Summary of Conversations:

As noted within the report shown above.

### Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Ady Velasco, (818) 292-0659, who represents the Office of Structural Materials for your project.

---

<b>Inspected By:</b>	Dixon,Roscoe	Quality Assurance Inspector
<b>Reviewed By:</b>	Cochran,Jim	QA Reviewer

---